

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

144  
NE  
1/4-1/2  
0.256 mi.  
1352 ft.

GULF SERVICE STATION  
2890 SHELL ROAD  
BROOKLYN, NY

NY LTANKS  
NY AST  
NY Spills  
U003080330  
N/A

Relative:  
Higher

Actual:  
3 ft.

LTANKS:

Name: SAM'S SHELL ROAD SERVICE  
Address: 2890 SHELL ROAD  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9610623 / 2007-01-03  
Facility ID: 9610623  
Site ID: 304458  
Spill Date: 1996-11-25  
Spill Cause: Tank Failure  
Spill Source: Gasoline Station or other PBS Facility  
Spill Class: B3  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: rmpiper  
Referred To: Not reported  
Reported to Dept: 1996-11-25  
CID: 266  
Water Affected: Not reported  
Spill Notifier: Other  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: True  
Remediation Phase: 0  
Date Entered In Computer: 1996-11-25  
Spill Record Last Update: 2007-01-03  
Spiller Name: MIKE MAZZA  
Spiller Company: SAM'S SHELL ROAD SERVICE  
Spiller Address: 2890 SHELL ROAD  
Spiller County: 001  
Spiller Contact: MIKE MAZZA  
Spiller Phone: Not reported  
Spiller Extension: Not reported  
DEC Region: 2  
DER Facility ID: 245954  
DEC Memo: "1/3/07- DECP iper reviewed report of additional soil removal conducted by PTC. An additional 32 tons of soil was removed and endpoints are clean of VOC's though SVOC's related to urban fill was detected. Based on additional work, report, analytical, this spill is closed. 9/6/06- DEC Piper mailed Letter to Shell rd LLC. stating requirements. Soil and gw delineation, PBS info update. 9/5/06- DEC Piper reviewed Phase II from F & N Env. As per analytical gross soil contamination exists on site as well as exceedances in gw. Soil and gw must be fully delineated. Additionally 5 additional tanks were discovered on the property and must be registered. 8/29/06- DEC Piper Spill tranferred to Piper from Dyber. DEC Piper reviewed letter from PTC. PTC recommends closure though there sre elevated levels in both soil and gw. Analytical received though no written report. Original report performed by Fenley and Nichol. Piper contacted F & N to obtain full report w/ recommendations. Additional investigation needed. 3/30/06, Dyber: Received Subsurface Investigation Report. Next step: Review investigation report. 2/24/06, Dyber: Oversaw fieldwork at site. 1/17/06, Dyber: Approved Investigation plan.  
10/24/05, Dyber: Received request for extension and FOIL request from

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Mark Turoff (718-257-8470). Left message. 10/11/05, Dyber: Received call from David Oloke from Fenley & Nicol, who was hired by property owner. I told him that we require endpoint samples. He will call back with field work date. 10/6/05, Dyber: Received further information from Atty. Nick Gravante (718-236-4500). Still need endpoint samples. I told Nick to hire an environmental consultant and ask the consultant to contact me. 8/30/05, Dyber: Sent letter requesting endpoint samples or investigation work plan by 9/30. 8/9/05, Dyber: I told Mike Mazza that he must provide endpoint sampling results or we will require sampling. 8/3/05: Mark Turoff called back. He has not kept any records of this job. 7/26/05 & 8/3/05, Dyber: No call back from Turoff - left messages. If no return, determine if spill will be left open. 7/18/05, Dyber: Spoke with Mark Turoff of Energy Tank & Environmental (917-750-1843). He will check his records for endpoint sampling results and get back to me. 7/15/05: Received disposal receipts and invoice from Mike Mazza. He does not have endpoint sampling results. Left message for Mark Turoff; will ask him to provide endpoint results. 6/14/05: Spoke with Michael Mazza. He will send documentation that spill was cleaned up. 6/10/05: PBS Facility No. 2-063029. Gasoline tanks were all removed. As the tank failure was for a gasoline tank, must get documentation of removal & clean soil. Call Michael Mazza, operator, next week at (718) 996-0331 or (718) 372-1480. Prior to Sept, 2004 data translation this spill Lead\_DEC Field was ROMMEL This spill was reassigned from DEC Sigona to Rommel on January 7, 2004. 12/16/97 REASSIGNED TO SIGONA 11/25/96 PER VINNIE, THE SOIL WAS DUG OUT & COVERED IN PLASTIC FOR THIS EVENING.KSW"

Remarks:

"FOUND CONTAMINATED SOIL DURING TANK REMOVAL. SOIL TO BE STOCKPILED AS NECESSARY."

All Materials:

Site ID: 304458  
Operable Unit ID: 1042052  
Operable Unit: 01  
Material ID: 342838  
Material Code: 0009  
Material Name: gasoline  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

AST:

Name: SAMS NEPTUNE SERVICE STATION  
Address: 2890 SHELL ROAD  
City,State,Zip: BROOKLYN, NY 11224  
Region: STATE  
DEC Region: 2  
Site Status: Active  
Facility Id: 2-063029  
Program Type: PBS  
UTM X: 586732.08849  
UTM Y: 4492884.70310  
Expiration Date: 05/28/2008  
Site Type: Retail Gasoline Sales

Affiliation Records:

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Site Id: 1223  
Affiliation Type: Facility Owner  
Company Name: MICHAEL MAZZA  
Contact Type: Not reported  
Contact Name: Not reported  
Address1: 133 BAY 34TH STREET  
Address2: Not reported  
City: BROOKLYN  
State: NY  
Zip Code: 11214  
Country Code: 001  
Phone: (718) 372-1480  
EMail: Not reported  
Fax Number: Not reported  
Modified By: TRANSLAT  
Date Last Modified: 2004-03-04

Site Id: 1223  
Affiliation Type: Mail Contact  
Company Name: SAMS NEPTUNE SERVICE STATION  
Contact Type: Not reported  
Contact Name: MICHAEL MAZZA  
Address1: 2890 SHELL ROAD  
Address2: Not reported  
City: BROOKLYN  
State: NY  
Zip Code: 11224  
Country Code: 001  
Phone: (718) 996-0331  
EMail: Not reported  
Fax Number: Not reported  
Modified By: TRANSLAT  
Date Last Modified: 2004-03-04

Site Id: 1223  
Affiliation Type: Facility Operator  
Company Name: SAMS NEPTUNE SERVICE STATION  
Contact Type: Not reported  
Contact Name: MICHAEL MAZZA  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (718) 996-0331  
EMail: Not reported  
Fax Number: Not reported  
Modified By: TRANSLAT  
Date Last Modified: 2004-03-04

Site Id: 1223  
Affiliation Type: Emergency Contact  
Company Name: MICHAEL MAZZA  
Contact Type: Not reported  
Contact Name: MICHAEL MAZZA  
Address1: Not reported  
Address2: Not reported  
City: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (718) 372-1480  
EMail: Not reported  
Fax Number: Not reported  
Modified By: TRANSLAT  
Date Last Modified: 2004-03-04

Tank Info:

Tank Number: 007  
Tank Id: 50929  
Material Code: 0022  
Common Name of Substance: Waste Oil/Used Oil

Equipment Records:

A00 - Tank Internal Protection - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
I00 - Overfill - None  
D00 - Pipe Type - No Piping  
J00 - Dispenser - None  
G00 - Tank Secondary Containment - None

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.  
Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported  
Install Date: Not reported  
Capacity Gallons: 200  
Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: TRANSLAT  
Last Modified: 04/14/2017  
Material Name: waste oil/used oil

SPILLS:

Name: GULF SERVICE STATION  
Address: 2890 SHELL ROAD  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 9708341 / 1997-10-16  
Facility ID: 9708341  
Facility Type: ER  
DER Facility ID: 245954  
Site ID: 304459  
DEC Region: 2  
Spill Cause: Deliberate  
Spill Class: D4  
SWIS: 2401  
Spill Date: 1997-10-09  
Investigator: SMMARTIN  
Referred To: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Reported to Dept: 1997-10-16  
CID: 266  
Water Affected: COONEY ISLAND CREEK  
Spill Source: Commercial/Industrial  
Spill Notifier: Local Agency  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1997-10-16  
Spill Record Last Update: 1997-10-17  
Spiller Name: Not reported  
Spiller Company: LOUIS COLICCHIO  
Spiller Address: 523 EAST 86TH STREET  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
MARTINKAT mmm REFER TO SPDES (CHAN)."  
Remarks: "COIN OPERATED CAR WASH MACHINE AT LOCATION DISCHARGES INTO THE  
CREEK. SPILLER IS THE OWNER OF THE MACHINE."  
All Materials:  
Site ID: 304459  
Operable Unit ID: 1051567  
Operable Unit: 01  
Material ID: 330322  
Material Code: 0060A  
Material Name: wastewater  
Case No.: Not reported  
Material FA: Other  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported